# INDUSTRIAL CABLES

## PART NUMBER REFERENCE MI-X

M12

### Select Connector Type: End "1"

#### REFER TO GigE PAGE 6 = RJ

- 5P Male = A
- 5P Female = B
- 8P Male = C
- 8P Female = D
- 12P Male = E 12P Female = F
- 17P Male = G
- 17P Female = H
- I/F Female = F

#### **Connector Orientation for Types A-H:**

- Straight = 0
- R/A **UP** = 1
- R/A **RIGHT** = 3
- R/A **DOWN**= 5
- R/A **LEFT** = 7

### **Cable Type Options:**

- 28 AWG x 5C = 1
- 28 AWG x 8C = 2
- 24 AWG x 12C = 3
- 28 AWG x 17C = 4
- CAT 6 SSTP G1 = 5

#### Select Connector Type: End "2"


- 5P Male = A
- 5P Female = B
- 8P Male = C
- 8P Female = D
- 12P Male = E
- 12P Female = F
- 17P Male = G
- 17P Female = H
- Flying Leads = X

#### **Option: Length in Meters**


REV. C

- 24 - COMPONENTS EXPRESS, INC. CABLE SOLUTIONS GUIDE


M




M12 Straight PROFILE




M12 R/A PROFILE




**REV.** C




MI-FO-3-X-( )M



MI-F5-3-X-( )M



**REV.** C



162150500-( )M • M12 Female 12-Pin Custom Y Adaptor - USB & VGA

